

Australian BORDER FORCE

# Asbestos & the role of the ABF

### Contents

- Role of ABF
- Recent detections
- Importer & exporter responsibilities
- Awareness & information



### I get where you're coming from...



Australian Border Force

### **Asbestos Video News Release**



### **Role of Australian Border Force**



- Asbestos prohibition commenced December 2003
- ABF administers border controls
- Department of Jobs & Small
  Business is responsible for policy
- Intelligence informed & risk based approach
- 100% of goods imported into Australia are risk assessed

## **Compliance & Enforcement Measures**

- > ABF promotes voluntary compliance
- Responses to non-compliance include:
  - Advice
  - Education
  - Checks
  - Seizure
  - Infringement notices
  - Prosecution



### Responsibilities

### **Importers & exporters must:**

- Ensure goods do not contain asbestos
- Understand their supply chains and production processes
- Be aware of differences in overseas definitions & standards





# Testing

- Provides assurance & helps protect community
- Not intended to penalise importers

### In Australia

Use a NATA accredited laboratory



### **Outside Australia**

Samples may be tested before goods are imported

- Laboratory accredited by NATA recognised equivalent
- Must be from same shipment & indicate presence of <u>any</u> asbestos

### **Asbestos Detections at the Border**









Motor vehicles & parts
 Brake pads & gaskets
 A prefabricated building
 Building products

#### Australian Border Force nabs Maseratis

March 22, 2018

story photos

story photos





To whom it may concern

Unit 8 Claggy Road Kimpton Hertfordshire SG4 8QB

> +44 (0)1438 832161 +44 (0)1438 833695 service@mcgrathmaserati.co.uk mcgrathmaserati.co.uk

#### 27/11/17

TO

#### Re: Declaration of Asbestos free.

This letter confirms that the Maserati cars listed below have been looked after by McGrath Maserati in the UK for many years and all are in regular use.

|  | Car  | Registration   | Owner |
|--|--|--|-------|
| 1964<br>1972<br>1972<br>1972<br>1972<br>1974 | Maserati 5000 GT<br>Maserati Bora 4.7<br>Maserati Indy 4.7<br>Maserati Ghibli SS<br>Maserati Quattroporte Frua | EBY 533B<br>EWV 357L<br>11 NDY<br>RBY780K<br>AVS798N |       |
| 2009<br>1971<br>2004                         | Maserati Quattroporte Bellagio<br>Maserati Ghibli SS<br>Maserati 4200 Spyder                                   | LK60 KCU<br>SVR 311H<br>AT54 GZZ                     |       |

MM

We have undertaken restoration, either complete or partial, of all the pre-2003 cars and all asbestos-bearing parts have been replaced. To the best of our knowledge, none of these cars (pre or post 2003) contain any asbestos.

We have also undertaken a program with our suppliers to ensure they have supplied us only with parts which are asbestos free and can provide further in formation if required.

Yours sincerely,

WHOM IT MAY CONCERN MM

Unit 8 Claggy Road Kimpton Hertfordshire SG4 8QB

+44 (0)1438 832161 +44 (0)1438 833695 service@mcgrathmaserati.co.uk mcgrathmaserati.co.uk

13/12/2017

#### MASERATI GHIBLI SS

**REGISTRATION- RBY 780K** 

<u>COLOUR</u>- GREEN

CHASSIS NO.- AM115/49\*2506\*

ASBESTOS COMPLIANCE

BRAKE PADS-SEE COMPLIANCE LETTERS FROM SUPPLIERS-MIE, PAGID, TRW.

<u>CLUTCH PLATE</u>-SEE COMPLIANCE LETTERS FROM SÙPPLIERS-AP CLUTCH via ASTON MARTIN LAGONDA LTD via RAICAM CLUTCH LTD.

<u>HEAD GASKET</u>-SEE COMPLIANCE LETTER FROM SUPPLIER-MIE CORPORATION

<u>ALL OTHER GASKETS</u>-SEE COMPLIANCE LETTER FROM SUPPLIER-RAM GASKET SOLUTIONS LTD

EXHAUST-SEE COMPLIANCE LETTER FROM SUPPLIER-P.D.GOUGH & CO.LTD

<u>HEAT SHIELD & SLEAVING</u>- SEE COMPLIANCE LETTER FROM SUPPLIER-DESIGN ENGINEERING, INC. (DEI)

Registered In England No; 5059222 Registered Office as above Vat Registration Number; 829 9805 72



August 25,2017

McGrath Maserati Unit 8 Claggy Road Herts Kimpton SG48QB UNITED KINGDOM

Based on our conversation this week, I examined your purchase history and am confident that none of the parts sold by MIE Corporation contain asbestos. None of the supplied parts, that historically contained asbestos, were manufactured prior to the time asbestos was banned. And, all of the suppliers we use currently manufacture these parts with non-asbestos, modern alternative materials.

Please let me know if you require any additional information on this matter.

Sincerely,





McGrath Maserati Unit 8 Claggy Road Herts Kimpton SG48QB UNITED KINGDOM

Based on our conversation this week, I examined your purchase history and am confident that none of the parts sold by MIE Corporation contain asbestos. None of the supplied parts, that historically contained asbestos, were manufactured prior to the time asbestos was banned. And, all the suppliers we use currently manufacture these parts with non-asbestos, modern alternative materials.

Here is a list of parts we have supplied to McGrath Maserati. None of them contain asbestos.

| Manufacturer       | Part Description                 | Part number   | Contains Asbestos?<br>Yes or No |
|--------------------|----------------------------------|---------------|---------------------------------|
| Various            | Brake pads set –<br>front & rear | 71163 & 71164 | NO                              |
| Ehlring            | Engine gaskets –<br>head seal    | 62823 & 62822 | NO                              |
| Various            | Rubber seals                     | Various       | NO                              |
| Various            | Rubber suspension<br>parts       | Various       | NO                              |
| Various            | Rubber hoses                     | Various       | NO                              |
| Remflex            | Paper gaskets                    | Various       | NO                              |
| Various            | Engine Bearings                  | Various       | NO                              |
| Various            | Distributor cap &                | Various       | NO                              |
| Various            | Ignition Wire set                | Various       | NO                              |
| Various<br>Coleman | Brake Disc                       | Various       | NO                              |
| Various            | Clutch slave<br>cylinder         | Various       | NO                              |
| Various            | Steering tie rod                 | Various       | NO                              |

Australian I

1620 Industry Drive SW, Suite F • Auburn, WA 98001 • USA Tel: USA + (253)-833-2598 Fax: USA + (253) -735-0946 Email: <u>mci@mascratinet.com</u> Website <u>http://www.mascratinet.com</u>

ooter] 14

Sec. 1.

| PAGID   | BRAKE | PADS |
|---------|-------|------|
| I FICID |       |      |





#### MATERIAL SAFETY DATA SHEET

HMIS RATINGS: 1-0-0-E PAGE 1 of 3

#### May be used to comply with OSHA's Hazard Communication Standard 29 CFR 1910, 1200. Standard must be consulted for specific requirements.

The product identity on this page meets the OSHA definition of an article and is exempt from the Hazard Communication Standard as to The ingredients in these products are resin bonded and hazards normally associated with contact to pure dusts of the listed ingredients all normally careful uses. Some potential may exist for exposure to dust. should not be significant. Federal Mogul has listed all of the essential ingredients present in a series of products of this general should not be agrinited in a containing on this instea an or the essential ingredients present in a series of produces of this general description. All products identified on this MSDS are assestos free. The friction materials listed below will not contain all of the

ingredients shown below. The recommended exposure limits are those for the most hazardous substance in a class of substances. Exact ingreurence shown below. The recommenced exposure limits are mose for the most nazaroous substance in a class of substances. Exact formulation is considered proprietary and confidential. Precise product information will not be disclosed, other than to a health professional in accordance with the regulations, without an approved Secrecy Agreement. The information herein is believed to be accurate, however, Federal Mogul makes no representation or warranty as to its accuracy. This data is furnished gratultously and independently of any sale of the product, and only for outsomer investigation and independent verification. Foundation gradienceasy and interpendently or any sale or the product, and only for customer investigation and independent vernication. Federal Mogul shall in no event be responsible for any damages of whatever nature directly or indirectly resulting from the publication or receival mogui shall in no event be responsible for any damages of whatever nature directly or indirectly resulting from the publication or use of or reliance upon data contained herein. No express or implied warranty of any kind, including warranties of merchantability or fitness for use with respect to the product or to the data herein is made hereunder. IDENTITY (As Used on Label or on Friction Material) NA-27 (A, W), 927A, 929A, 931-(66, 83, 92, 162), 987-(6, 6B), 1027-138, 1048-(9, 109, 111), 1083-(7, 49, 63), 1143-(3, 153M, 155, 162M, 301, 320M), 1135-8, 1155-(2, 2H, 61, 155, 169), 1153-5, 1157-14, 1162-15, 1175-8, 1177-9, 1182-95, 1184-41, 1189-10, 1194-3, 1199-17, 1223-44, 124-(66, 78), 1226-(7, 16, 17), 1272-15, 1273-48, 3006-27, 3027-(73, 85, 91, 91B, 91CP), 108, 127), 3030-(6, 7, 67CP, 114, 153, 15B, 160, 1274-(66, 78), 1226-(7, 16, 17), 1272-15, 1273-48, 3006-27, 3027-(73, 85, 91, 91B, 91CP), 108, 127), 3030-(6, 7, 67CP, 114, 153, 15B, 160, 107, 1226, 126A, 1226, 137, 1236-(7, 10, 15), 143, 163, 173, 158, 160, 107, 1226, 1220, 1228), 3079-(67, 70, 13, 14, 16, 17, 36), 3080-21, 137, 212, 227, 250), 3041-29, 3050-(3, 19), 3059-(52, 52A, 91, 100, 100A, 120, 120A, 122A), 3079-(67, 70, 13, 14, 16, 17, 36), 3080-21, 137, 212, 227, 250), 3041-29, 3050-(3, 19), 3059-(52, 52A, 91, 100, 100A, 120, 120A, 122A), 3079-(67, 70, 13, 14, 16, 17, 36), 3080-21, 137, 212, 247, 266, 56A), 3115-(4, 5, 18, 23, 36, 40, 48, 49, 131), 3153-1, 3156-1, 3158-16, 3152- (21, 22, 26, 27), 3164-(4, 9), 4306-3, 3170-104, 120, 120, 120A, 120, 120A, 120, 120A, 120, 120A, 120, 120A, 1

 BEX-(647, 665, 669, 697, 6000, 6008-1, 6008-15, 6009, 6011, 6020, 6024, 6028, 6029, 6033, 6035, 6036, 6037, 6040, 6042, 6043, 6097, 6048, 6053, 6054, 6055, 6056, 6058, 6069, 6069, 6092, 6074, 6076, 6078, 6079, 6080, 6082, 6085, 6087, 6038, 6089, 6092, 6048, 6053, 6054, 6055, 6056, 6058, 6068, 6064, 6068, 6074, 6076, 6078, 6079, 6080, 6082, 2084, 2085, 2042, 2082, 2023, 2027, 2029, 2031, 2034, 2035, 2042, 175, SM, VL20, VL23), ABH-(281, 282, 285, 294, 295, 2094, 2015, 2019, 2022, 2023, 2027, 2029, 2031, 2034, 2035, 2041, 2042, 2047, 2049, 2050, 2052, 2054, 2056, 2063, 2069, 2071, 2005, 2015, 2019, 2022, 2023, 2027, 2029, 2031, 2034, 2035, 2041, 2042, 2047, 2049, 2050, 2052, 2054, 2056, 2063, 2069, 2071, 2005, 2015, 2019, 2022, 2023, 2027, 2029, 2031, 2034, 2035, 2044, 3020, 3024, 30043, 3044, 3048, 3054, 4000, 2033-1, 2005, 2015, 2015, 2018, 392-1, 2030, 3009, 3013, 3014, 3013, 3020, 3024, 3005, 3040, 3042, 3044, 4000, 1020, 4005, 40074, 4003, 40171, 1975, 1845, 392-1, 1975, 1220, 1215, 1220, 1215, 1220, 1215, 1220, 1215, 1220, 1215, 1220, 1215, 1230, 1240, 1250, 1255, 1280, 1270, 1275, 1290, 1320, 1320, 1330, 1350, 1360, 1475, 1490, 147, 420, 421, 500, 1365, 1360, 1475, 1490, AR-(1 2), ASAA-2171, BDX-2171, CIV 20, 2014, 2013, 2003, 3003, 4000, 4005, 4006, 4006, 4006, 4010, Met, 1340, 1350, 1360, 1475, 1490, 141, 140, 242, 421, 2007, 2022, 2031, 2001, 3022, 3039, 3001, 3022, 3059, 3061, 3062, 3053, 3064, 3153, 501, 600, 601, 700, 701, 711, 711, 800, 801, 1101), FA (14, 16, 22, 28, 34, 657, 3010, 3022, 3039, 3004, 3054, 3053, 501, 600, 601, 700, 701, 710, 711, 800, 801, 1101), FA (14, 16, 22, 28, 34, 657, 3010, 3022, 3059, 3061, 3062, 3053, 3004, 3153, 501, 600, 601, 700, 701, 710, 711, 800, 801, 1101), FA (14, 16, 22, 28, 286, 286-1, 456, 478, 718, 973, 8071, NS-(1200, 1205, 3142, 3219, 4008), FM (200, 200-1, 206, 712, 835, 592-1, 2003, 1207, 2022, 2031, 2048, 2073, 2074, 2075, 2078, 2077, 1285, 1269, 2237), PMT; PM17/20-1, PM23-11, FA OE (456, 718, 687), FIC (20, 23), FI (20, 23), FI (20,

| ORG, GLD, SLV), R-(201, 203, 204, 205, 200, 001, 1   |                                      |  |
|--|--------------------------------------|--|
| SOR215, S  | ECTION I                             | mber: (540) 662-3842                     |
| 经济收益 网络拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉拉  | T Fur angenov Telenhone INU          |  |
|  | Telephone Number for Info            | smallon (o lor                           |
|  |                                      | 1144 2005                                |
| Address: (Number, Street, City, State, Zip Code)   | Date Prepared: A                     | pril 11, 2005<br>P. Kwolek / Dick Hummel |
|  |                                      | P. KWOICK / DICK HUMIN                   |
| Winchester, VA 22604<br>SECTION II - Hazardous   | Ingredients / Identity Inform        | ation                                    |
| SECTION II - Hazardous   | MINIMUM                              | MINIMUM                                  |
| (Hazardous and non)  | OSHA PEL                             | ACGIH ILV                                |
| All Components (nazar de la common Names)<br>(Specific Chemical Identity: Common Names)  |                                      | 5.0 mg/M <sup>3</sup>                    |
|  |                                      |  |
| Phenolic, Cashew, Elastomeric, Linsaed Compounds,<br>Vitreous and Non Vitreous Fibers: organic and inorgan<br>Barytes, Calcium Carbonate, Mica, Iron Chromite (triva<br>Barytes, Calcium Carbonate, Ferrophosphorus, Fuller: | lent chromium), Amorphous silica,    | Marmiculite                              |
| Vitreous and Non Vitreous Fibers: organic and Morgan<br>Baryles, Calcium Carbonate, Mica, Iron Chromite (triva<br>Sodium hexametaphosphate, Ferrophosphorus, Fuller:<br>Sodium hexametaphosphate, Auminum Oxide, Magnesi     | s earth, Portland Cement, Slag Wool, | ia Stagi, Zinc Oxide)                    |
| Sodium nexametaphoophater thuring Oxide Magnesi  | um Oxide, Iron, Iron oxideor         | 2.0 mg/M <sup>3</sup>                    |
| Metal/Metal Oxides: (Aluminum, Aluminum, Carbon black, Graphites, C<br>Carbon Products: (Carbon, Carbon black, Graphites, C  | oke, Coal) 2.0 mg/w                  |  |
| Carbon Products: (Carbon, Carbon black, Graphites, C<br>Talc, Kyanite, Rottenstone, Lime, Mica, Mineral fibers   | (exempt), woilastonic, 200           | 1 fiber /cm <sup>3</sup>                 |
| Inorganic (biosoluable) fibers   | 1.0mg/M <sup>3</sup>                 | 1.0 mg/M <sup>3</sup>                    |
| Copper, Zinc, Brass fibers and chips   | 0.5 mg/M <sup>3</sup>                | 0.5 mg/M <sup>3</sup>                    |
| Chrome green oxide   | 0.5 fibers/cm <sup>3</sup>           | 0.5 fibers/cm                            |
| Chrome green oxido   | 0.3 mg/M <sup>3</sup>                | 0.3 mg/M                                 |
| Ceramic fibers   |                                      | 0.005 mg/M°                              |
| Quartz, Tripoli<br>Lead (<0.025% in brass chips only, < 0.25% in formu   | ila) 0.005 mg/M                      | PRINT DATE: 02/19/2007                   |
| Lead (<0.025% In brass on po on pr   |                                      |  |

Australian Border Force

FORM: WIN-EHS-MS-019-21B

Bey. ISSUE: 07/21/2006

# **Awareness & Information**

### **Rapid Response Protocol**

Information sharing across jurisdictions


### **Communication Channels**

- Goods Compliance Update
- Compliance Advisory Group
- ➤ Website
- Fact sheets & Notices
- Industry forums
- Media releases



### **Asbestos information page**

https://www.homeaffairs.gov.au/Busi/cargo-support-trade-and-goods/importing-goods/prohibited-and-restricted/asbestos





) 🈂 https://www.homeaffairs.gov.au/Importingandbuyinggoodsfromoverseas/Documents/fs-asbestos-risk-importing-vehicle.pdf

– **ව X** බබසි

File Edit Goto Favorites Help 🍰 🗱 ABC News 🗿 Canberra Times Ġ Google 🕜 Guardian



# Managing the risk of asbestos when importing a motor vehicle

#### The border control

The health risks posed by exposure to asbestos are well known. An Australia-wide ban on the manufacture and use of all forms of asbestos took effect on 31 December 2003 to protect the Australian community. A border control for asbestos was enacted at the same time to prevent the unlawful importation of asbestos, and goods containing asbestos.

📲 🎗 🖽 🤮 🔚 🌈 💁 🍕 🌉 🖉 🖊

# Thank you

### Website www.homeaffairs.gov.au



### Border Watch Phone: 1800 009 623



Australian Border Force